

## **JARVIS INDUSTRIES LIMITED**

# Safety Data Sheet

# Everest Trade High Build Epoxy Floor Paint - Part A

## **SECTION 1: Identification**

## 1.1 GHS Product identifier

Product name Everest Trade High Build Epoxy Floor Paint - Part A

Product number EVEINDEPX - EVEEPOXAN - EVEGAREPX

Brand Everest Trade Paints

#### 1.3 Recommended use of the chemical and restrictions on use

Floor Coating

## 1.4 Supplier's details

Name Jarvis Industries Limited Address Walkers Industrial Park

Ollerton Road

NG22 OPQ Tuxford Nottinghamshire

United Kingdom

Telephone 0800 043 8220

email accounts@jarvisindustries.co.uk

## 1.5 Emergency phone number

0800 043 8220

## **SECTION 2: Hazard identification**

### 2.1 Classification of the substance or mixture

#### GHS classification in accordance with: UK REACH Regulation

- Serious eye damage/eye irritation, Cat. 2
- Skin corrosion/irritation, Cat. 2

## Everest Trade High Build Epoxy Floor Paint - Part A

- Skin sensitizer, Cat. 1

### 2.2 GHS label elements, including precautionary statements

#### **Pictograms**



1. Exclamation mark; 2. Environment

Signal word Warning

Hazard statement(s)

H315 Causes skin irritation

H317 May cause an allergic skin reaction
H319 Causes serious eye irritation

Precautionary statement(s)

P261 Avoid breathing dust/fume/gas/mist/vapors/spray.

P264 Wash ... thoroughly after handling.

P272 Contaminated work clothing should not be allowed out of the workplace.
P280 Wear protective gloves/protective clothing/eye protection/face protection.

P302+P352 IF ON SKIN: Wash with plenty of water/...

P305+P351+P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact

lenses, if present and easy to do. Continue rinsing.

P321 Specific treatment (see ... on this label).

P332+P313 If skin irritation occurs: Get medical advice/attention.

P333+P313 If skin irritation or rash occurs: Get medical advice/attention.

P337+P313 If eye irritation persists: Get medical advice/attention.
P362+P364 Take off contaminated clothing and wash it before reuse.

P501 Dispose of contents/container to ...

## SECTION 3: Composition/information on ingredients

## 3.2 Mixtures

#### Components

## 1. EPOXYRESIN, reaction product: BISPHENOL-A(EPICHLOROHYDRIN), average molecule wei

 Concentration
 50 - 70 % (weight)

 EC no.
 500-033-5

 CAS no.
 25068-38-6

 Index no.
 603-074-00-8

- Skin corrosion/irritation, Cat. 2

- Serious eye damage/eye irritation, Cat. 2
- Skin sensitizer, Cat. 1
- Hazardous to the aquatic environment, long-term (chronic), Cat. 2

H315 Causes skin irritation

## Everest Trade High Build Epoxy Floor Paint - Part A

H317 May cause an allergic skin reaction

H319 Causes serious eye irritation

H411 Toxic to aquatic life with long lasting effects

Eye Irrit. 2; H319:  $C \ge 5 \%$ Skin Irrit. 2; H315:  $C \ge 5 \%$ 

### 2. Formaldehyde, polymer with 2-(chloromethyl)oxirane and phenol

 Concentration
 25 - 35 % (weight)

 EC no.
 500-006-8

 CAS no.
 9003-36-5

### 3. Alkyl epoxy resin

SCLs/M-factors/ATEs

 Concentration
 10 - 20 % (weight)

 EC no.
 271-846-8

 CAS no.
 68609-97-2

 Index no.
 603-103-00-4

- Skin corrosion/irritation, Cat. 2

- Skin sensitizer, Cat. 1

H315 Causes skin irritation

H317 May cause an allergic skin reaction

#### **SECTION 4: First-aid measures**

#### 4.1 Description of necessary first-aid measures

General advice In case of accident or if you feel unwell, seek medical advice immediately (show the

SDS where possible).

If inhaled Remove victim to fresh air and keep at rest in a position comfortable for breathing.

If not breathing, if breathing is irregular orifrespiratory arrest occurs, provide articial respiration or oxygen by trained personnel. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Get medical attention if adverse health effects persist or are severe. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen

tight clothing such as a collar, tie, belt or waistband.

In case of skin contact Wash with plenty of soap and water. Remove contaminated clothing and shoes.

Wash contaminated clothing thoroughlywith water before removing it, or wear gloves. Continue to rinse for at least 10 minutes. Get medical attention. In the event of any complaints or symptoms, avoid further exposure. Wash clothing

before reuse. Clean shoes thoroughly before reuse.

# Everest Trade High Build Epoxy Floor Paint - Part A

In case of eye contact Immediately ush eyes with plenty of water, occasionally lifting the upper and lower

eyelids. Check for and remove any contact lenses. Continue to rinse for at least 10

minutes. Get medical attention.

If swallowed Wash out mouth with water. Remove dentures if any. Remove victim to fresh air

and keep at rest in a position comfortable for breathing. If material has been swallowed and the exposed person is conscious, give small quantities of waterto drink. Stop ifthe exposed person feels sick as vomiting may be dangerous. Do not induce vomiting unless directed to do so by medical personnel. If vomiting occurs, the head should be kept low so that vomit does not enterthe lungs. Get medical attention if adverse health effects persist or are severe. Never give anything by mouth to an unconscious person. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such

as a collar, tie, belt or waistband.

Personal protective equipment for first-aid responders

No action shall be taken involving any personal risk or without suitable training. It

may be dangerous to the person providing aid to give mouth-to-mouth

resuscitation. Wash contaminated clothing thoroughly with water before removing

it, or wear gloves.

### 4.2 Most important symptoms/effects, acute and delayed

The most important known symptoms and effects are described in the labelling (see section 2) and/or in section 11

### 4.3 Indication of immediate medical attention and special treatment needed, if necessary

Notes to physician: Treat symptomatically. Contact poison treatment specialist immediately iflarge quantities have been ingested or inhaled.

## **SECTION 5: Fire-fighting measures**

#### 5.1 Suitable extinguishing media

Use an extinguishing agent suitable for the surrounding area.

### 5.2 Specific hazards arising from the chemical

Hazards from the substance or mixture: In a fire or if heated, a pressure increase will occur and the container may burst. This material is toxic to aquatic life with long lasting effects. Fire water contaminated with this material must be contained and prevented from being discharged to any waterway, sewer or drain.

Hazardous thermal decomposition products: Decomposition products may include the following materials: Carbon dioxide, carbon monoxide, halogenated compounds.

## 5.3 Special protective actions for fire-fighters

Special protective actions for Fire-fighters: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is are. No action shall be taken involving any personal risk or without suitable training.

Special protective equipment for Fire-fighters: Fire-fighters should wear appropriate protective equipment and self- contained breathing apparatus (SCBA) with a fullface-piece operated in positive pressure mode. Clothing for Fire-fighters (including helmets, protective bootsand gloves) conforming to European standard EN 469 will provide a basic level of protection for chemical incidents.

#### **Further information**

Use water spray to cool unopened containers.

#### **SECTION 6:** Accidental release measures

#### 6.1 Personal precautions, protective equipment and emergency procedures

For non-emergency personnel: No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding

areas. Keep unnecessary and unprotected personnelfrom entering. Do not touch or walk through spilled material. Avoid breathing vapoor mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.

For emergency responders: If specialised clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel"d areas.

#### 6.2 Environmental precautions

Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air). Water polluting material. May be harmfulto the environmentifreleased in large quantities. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air). Water polluting material. May beharmfulto the environment if released in large quantities. Collect spillage.

#### 6.3 Methods and materials for containment and cleaning up

Small spill: Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water- insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.

Large spill: Stop leak if without risk. Move containers from spill area. Approach release from upwind. Prevent entry into sewers, water courses, basements or conned areas. Wash spillages into an euent treatment plant or proceed as follows. Contain and collect spillagewith non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in containerfor disposal according to localregulations. Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the samehazard as the spilled product.

### Reference to other sections

See Section 1 for emergency contact information

See Section 8 forinformation on appropriate personal protective equipment

See Section 13 for additional waste treatment information.

## **SECTION 7: Handling and storage**

#### 7.1 Precautions for safe handling

Protective measures: Put on appropriate personal protective equipment (see section 8 of SDS). Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Do not get in eyes or on skin or clothing.

Do not ingest. Avoid breathing vapor or mist. Avoid release to the environment. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Empty containers retain product residue and can be hazardous.

Do not reuse container

Advice on general occupational hygiene: Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures

## Everest Trade High Build Epoxy Floor Paint - Part A

#### 7.2 Conditions for safe storage, including any incompatibilities

Store in accordance with localregulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see section 10 of SDS) and food and drink. Keep containertightly closed and sealed untilready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination.

#### Specific end use(s)

Apart from the uses mentioned in section 1 no other specific uses are stipulated.

## SECTION 8: Exposure controls/personal protection

#### 8.1 Control parameters

- 1. Formaldehyde, polymer with 2-(chloromethyl)oxirane and phenol (CAS: 9003-36-5 EC: 500-006-8)
- 2. Alkyl epoxy resin (CAS: 68609-97-2 EC: 271-846-8)
- 3. EPOXYRESIN, reaction product: BISPHENOL-A(EPICHLOROHYDRIN), average molecule wei (CAS: 25068-38-6 EC: 500-033-5)

#### 8.2 Appropriate engineering controls

No special ventilation requirements. Good general ventilation should be sucient to control worker exposure to airborne contaminants. If this product contains ingredients with exposure limits, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure below any recommended or statutory limits

#### 8.3 Individual protection measures, such as personal protective equipment (PPE)

## **Pictograms**







#### Eye/face protection

Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: chemical splash goggles

#### Skin protection

Chemical-resistant, impervious gloves complying with an approved standard should be worn at alltimes when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specied by the glove manufacturer, check during use that the gloves are stillretaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.

#### **Body protection**

Wear protective clothing. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.

## Respiratory protection

## Everest Trade High Build Epoxy Floor Paint - Part A

Use a properly tted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary. Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator

#### Thermal hazards

No data available.

### Control banding approach

No data available.

#### **Environmental exposure controls**

Do not let product enter drains. Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.

## **SECTION 9: Physical and chemical properties**

#### Basic physical and chemical properties

Physical state Liquid

Appearance Pigmented Liquid

Color Varies Odor Typical

Odor threshold No data available.

Melting point/freezing point No data available.

Boiling point or initial boiling point and boiling range No data available.

Flammability No data available.

Lower and upper explosion limit/flammability limit No data available.

Flash point 150C

Explosive properties No data available.

Auto-ignition temperature 400C

Decomposition temperature No data available.

Decomposition temperature

Oxidizing properties

PH

No data available.

Vapor pressure

No data available.

Partition coefficient n-octanol/water (log value)

Vapor pressure

Evaporation rate

Density and/or relative density

Relative vapor density

No data available.

### Particle characteristics

No data available.

#### Supplemental information regarding physical hazard classes

No data available.

## Further safety characteristics (supplemental)

No data available.

## Everest Trade High Build Epoxy Floor Paint - Part A

## SECTION 10: Stability and reactivity

#### 10.1 Reactivity

Stable under normal conditions

#### 10.2 Chemical stability

Stable under normal conditions.

### 10.3 Possibility of hazardous reactions

Hazardous reactions or instability may occur under certain conditions of storage or use.

## 10.4 Conditions to avoid

Contact with incompatible materials. Sources of ignition. Exposure to heat.

## 10.5 Incompatible materials

No data available.

#### 10.6 Hazardous decomposition products

Under normal conditions of storage and use, hazardous decomposition products should not be produced.

### **SECTION 11: Toxicological information**

#### Information on toxicological effects

### Skin corrosion/irritation

May cause skin irritation. Signs/symptoms may include localized redness, swelling, and itching.

#### Serious eye damage/irritation

May cause eye irritation. Signs/symptoms may include redness, swelling, pain, tearing, and blurred or hazy vision.

### Respiratory or skin sensitization

No data available.

#### Germ cell mutagenicity

No data available.

### Carcinogenicity

This product is or contains a component that is not classifiable as to its carcinogenicity based on its IARC, ACGIH,NTP, or EPA classification

IARC: No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or potential carcinogen by IARC.

ACGIH: No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or potential carcinogen by ACGIH.

NTP: No component of this product present at levels greater than or equal to 0.1% is identified as a known or anticipated carcinogen by NTP.

## Everest Trade High Build Epoxy Floor Paint - Part A

OSHA: No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or potential carcinogen by OSHA.

This product is or contains a component that has been reported to be carcinogenicity based on its IARC, ACGIH,NTP, or EPA classification

IARC: No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or potential carcinogen by IARC.

ACGIH: No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or potential carcinogen by ACGIH.

NTP: No component of this product present at levels greater than or equal to 0.1% is identified as a known or anticipated carcinogen by NTP.

OSHA: No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or potential carcinogen by OSHA.

\_\_\_

Benzyl alcohol: IARC: No component of this product present at levels greater than or equal to 0.1% is identified as probable, possible or confirmed human carcinogen by IARC.

ACGIH: No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or potential carcinogen by ACGIH.

NTP: No component of this product present at levels greater than or equal to 0.1% is identified as a known or anticipated carcinogen by NTP.

OSHA: No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or potential carcinogen by OSHA.

#### Reproductive toxicity

No data available.

#### Summary of evaluation of the CMR properties

No data available.

#### Specific target organ toxicity (STOT) - single exposure

No data available.

### Specific target organ toxicity (STOT) - repeated exposure

No data available.

#### **Aspiration hazard**

No data available.

## SECTION 12: Ecological information

#### **Toxicity**

No data available.

## Persistence and degradability

No data available.

#### Bioaccumulative potential

## Everest Trade High Build Epoxy Floor Paint - Part A

No data available.

#### Mobility in soil

No data available.

#### Results of PBT and vPvB assessment

PBT/vPvB assessment not available as chemical safety assessment not required/not conducted

#### **Endocrine disrupting properties**

No data available.

#### Other adverse effects

No data available.

### **SECTION 13: Disposal considerations**

#### Disposal methods

#### Product disposal

The generation of waste should be avoided or minimised wherever possible. Disposal ofthis product, solutions and any by-products should at alltimes comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction.

Hazardous waste: The classication of the product may meet the criteria for a hazardous waste.

#### Packaging disposal

Methods of disposal: The generation of waste should be avoided or minimised wherever possible. Waste packaging should be recycled. Incineration orlandll should only be considered when recycling is not feasible.

Special precautions: This material and its container must be disposed ofin a safe way. Care should be taken when handling emptied containers that have not been cleaned orrinsed out. Empty containers orliners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers

## Waste treatment

Not available

### Sewage disposal

Do not dispose into the sewage systems

### Other disposal recommendations

Not available

## **SECTION 14: Transport information**

14.1 UN Number UN3082

14.2 UN Proper Shipping Name Environmentally hazardous substances, liquid, n.o.s.

9

Ш

14.3 Transport hazard class(es)

14.4 Packing group

## Everest Trade High Build Epoxy Floor Paint - Part A

#### **Environmental hazards**

Environmentally hazardous and/or marine pollutant: Yes

#### Special precautions for user

Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

#### Transport in bulk according to IMO instruments

Not available

## **SECTION 15: Regulatory information**

#### 15.1 Safety, health and environmental regulations specific for the product in question

#### SARA 302 Components

No chemicals in this material are subject to the reporting requirements of SARA Title III, Section 302

#### SARA 313 Components

This material does not contain any chemical components with known CAS numbers that exceed the threshold (De Minimis) reporting levels established by SARA Title III, Section 313.

## SARA 311/312 Hazards

No SARA Hazards

## Massachusetts Right To Know Components

No components are subject to the Massachusetts Right to Know Act.

#### Pennsylvania Right To Know Components

No components are subject to the Pennsylvania Right to Know Act.

#### New Jersey Right To Know Components

No components are subject to the New Jersey Right to Know Act.

#### California Prop. 65 Components

This product does not contain any chemicals known to State of California to cause cancer, birth defects, or any other reproductive harm.

## Canadian Domestic Substances List (DSL)

Chemical name: Phenol, 4,4'-{1-methylethylidene}bis-, polymer with (chloromethyl)oxirane CAS: 25068-38-6

#### Canadian Domestic Substances List (DSL)

Chemical name: Formaldehyde, polymer with (chloromethyl)oxirane and phenol

CAS: 9003-36-5

#### Canadian Domestic Substances List (DSL)

# Safety Data Sheet Everest Trade High Build Epoxy Floor Paint - Part A

Chemical name: Oxirane, mono[[C12-14-alkyloxy]methyl] derivs.

CAS: 68609-97-2

#### 15.2 Chemical Safety Assessment

This product contains substances for which Chemical Safety Assessments are stillrequired.

### **SECTION 16: Other information**

#### 16.1 Further information/disclaimer

DISCLAIMER: The information above is believed to be accurate and represents the best information currently available to us. However, we make no warranty of merchantability or any other warranty, express or implied, with respect to such information, and we assume no liability resulting from its use. Users should make their own investigation to determine the suitability of information for their particular purposes. In no event shall [COMPANY NAME] be liable for any claims, losses, or damages of any third party or for lost profits or any special, indirect, incidental, consequential or exemplary damages, whatsoever arising, even if Jarvis Industries Limited has been advised of the possibility of such damages.